

RECEIVED

FEB 08 2002

DIVISION OF  
OIL, GAS AND MINING

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210

Box 145801

Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291

Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 01/01 To (mo./yr.) 12/01
2. DOGM File Number (Mine No): 5 / 053 / 027
3. Mine Name: Black Ridge No. 1
4. Mineral(s) Mined (or permitted to mine): Picture Sandstone
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
1/4, 1/4, SW 1/4, Section 18, Township 42S, Range 14W  
1/4, 1/4, 1/4, Section , Township , Range  
1/4, 1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Thirstystone Resources Inc.
8. Permanent Street Address: 860 E 19th Street  
City, State, Zip: Tucson, AZ 85719  
Phone: 520/623-1396 Fax: 520/903-2265
9. Company Representative (or designated operator):  
Name: John Halton  
Title: President  
Business Address: 860 E 19th Street  
City, State, Zip: Tucson, AZ 85719  
Phone: 520/ 623-1398 Fax: 520/903-2265  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? 615



4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.  
Removed sandstone product from hillside quarry using drilling and blasting trackhoe and front end loader. An estimated 615 tons of picture sandstone and 2,877 tons of waste was removed. The waste was placed on previously distributed areas.
5. How much **additional acreage** was disturbed during the past year? None
6. How much acreage was **reclaimed** during the past year? None
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
N/A
8. What is the **total** disturbed acreage of entire project at years end? 2.90 acres
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
None planned.


**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print): John Halton  
 Title of Operator: President  
 Signature of Operator:   
 Date: 1/31/01

jb  
o:\forms\reports\MR-AR

**RECEIVED**

FEB 08 2002

DIVISION OF  
OIL, GAS AND MINING